



IF THIS LEAK IS SUSPECTED CHANGE THESE TWO O-RINGS AND TEST AGAIN.

**SHOCKER XLS**  
BODY CHANNEL LEAK GUIDE