

Two or more balls are being fed into the breech



POSSIBLE CAUSE: Ball Detents are damaged.

SOLUTION: Replace Ball Detents.