



The red area should have Red Loctite.

SHOCKER RSX

GRIP FRAME AREA LEAK