

www.buypmi.com



CAUTION

READ AND FOLLOW THE INSTRUCTIONS EXACTLY FOR ALL CARE AND CLEANING OF EXTREME RAGE X-RAY® PROTECTOR GOGGLE LENSES! IF YOU DO NOT UNDERSTAND OR HAVE ANY QUESTIONS REGARDING THESE INSTRUCTIONS CALL PMI AT (800) 579-1633.

EXTREME RAGE X-RAY® PROTECTOR Lenses are made of high-grade polycarbonate, the strongest optical material available. **IMPORTANT INFORMATION!** Your goggle lens will deteriorate, weaken and possibly break if you do not clean them exactly as instructed EVERY TIME YOU USE THEM!

Proper cleaning is the only way to keep EXTREME RAGE X-RAY® PROTECTOR Lenses strong and resistant to paintball impacts.

FOLLOW THESE INSTRUCTION CAREFULLY AND COMPLETELY!

CLEANING

A) Always clean your EXTREME RAGE X-RAY® PROTECTOR Lenses with PLAIN WATER or EXTREME RAGE Anti Fog Lens Cleaning Solution. NEVER USE ANYTHING ELSE!

WARNING! Never use cleaners such as Windex®, Fantastic®, Mr. Clean®, Spray 409® or any product with ammonia. Avoid contact with Gasoline, Acetone, Nail Polish Remover, Kerosene, etc.

CAUTION

Read and follow these instructions exactly. Use these instructions for all EXTREME RAGE X-RAY® GOGGLE LENSES. If you do not understand any part of these instructions or have any questions call PMI at (800) 579-1633.

NO GOGGLE CAN PREVENT FOGGING UNDER ALL CONDITIONS. IF YOUR GOGGLE DOES FOG,

DO NOT REMOVE IT WHILE ON THE FIELD.

EXTREME RAGE X-RAY® PROTECTOR LENSES are made from the strongest optical material made. Designed for excellent vision characteristics and protection. Proper cleaning and care is absolutely mandatory to retain this protection. Follow the instructions for lens care exactly to extend the life of this product.

These instructions apply to all EXTREME RAGE X-RAY® PROTECTOR Goggle Systems including units for personal use or field rental. If you are renting an EXTREME RAGE X-RAY® PROTECTOR Goggle System from a playing field always inspect it prior to use and return it to the field operator if it does not comply with the instructions contained within.

WARNING! Never use cleaners such as Windex®, Fantastic®, Mr. Clean®, Spray 409® or any product with ammonia. Avoid contact with Gasoline, Acetone, Nail Polish Remover, Kerosene, etc. These strong chemicals will weaken the lens and cause it to break.

If your EXTREME RAGE X-RAY® PROTECTOR Lens comes into contact with any of this type of substance or chemical fumes, **DO NOT USE IT!** Replace it with a new lens for your protection and discard the old lens immediately. **NEVER TAKE CHANCES!**

B) Always clean your goggle and lens with the **EXTREME RAGE Micro Fiber Lens Cloth** or soft cloth after every use. Take your goggle system apart by removing the lens from the frame. Wash all the paint residue from the lens, the goggle frame and inside the lens channel in the goggle frame with PLAIN WATER. Always wash each piece individually, even if you think it is clean. Always wash and dry each piece of your system completely prior to reassembly and use. Never allow any paint or paint spray to remain on your goggle system overnight.

1) Single Lens: Take your single lens out of the goggle frame and wash it with PLAIN WATER only. You can dry your lens with the **EXTREME RAGE Microfiber Lens Cloth** or soft cloth. Never use paper towel, newspaper or an abrasive cloth. Polycarbonate scratches easily. Be careful when handling your lens.

2) Thermal Lens: Take your thermal lens out of the goggle frame and gently wipe it with the **EXTREME RAGE Micro Fiber Lens Cloth** or



soft cloth. Never use paper towel, newspaper or an abrasive cloth. Polycarbonate scratches easily. Be careful when handling your lens. Never submerge this dual pane lens under water! **Never rub the soft inner lens surface** or apply any form of fog resistant solution to this side of the lens.

C) Use only **EXTREME RAGE Anti Fog Lens Cleaning Spray!** Never use any other brand of fog resistant spray on **EXTREME RAGE X-RAY®** Lenses as they may contain chemicals, which will damage the lens. Spray single lenses only with **EXTREME RAGE Anti Fog Lens Cleaning Spray;** allow standing for 15 seconds, then buff dry with a light circular motion using an **EXTREME RAGE Micro Fiber Lens Cloth.** Do not over buff lens, as it will remove anti fog coating.

WARNING! Never use unauthorized anti fog sprays or cleaners as they could contain chemicals that can damage or weaken your **EXTREME RAGE X-RAY® PROTECTOR** Lenses.

D) Always store your **EXTREME RAGE X-RAY® PROTECTOR** Goggle System in a cool dry place. Never store your goggle system near chemicals or fumes. Gasoline fumes and common cleaning solutions will damage your **EXTREME RAGE X-RAY® PROTECTOR** Goggle System and Lenses. Replace any **EXTREME RAGE X-RAY® PROTECTOR** Lens that has been exposed to these conditions.



READ COMPLETE OWNERS MANUAL PRIOR TO USE OF THE EXTREME RAGE X-RAY® PROTECTOR GOGGLE SYSTEM.

DO NOT DISCARD THESE INSTRUCTIONS.

THESE INSTRUCTIONS ARE IMPORTANT TO YOUR SAFETY

FOLLOW ALL INSTRUCTIONS FOR THE USE AND CARE OF THE EXTREME RAGE X-RAY® PROTECTOR GOGGLE SYSTEM TO PROLONG THE LIFE OF PRODUCT

NEVER REMOVE YOUR GOGGLES WHILE ON THE FIELD!

Pursuit Marketing Inc

55 Howard Ave, Des Plaines, IL 60018
Phone: (847) 233-9900 Fax: (847) 233-9901
www.buypmi.com

WARNING! Never store your **EXTREME RAGE X-RAY® PROTECTOR** Goggle System in a hot place such as a car trunk, near a heater or any heat source. High temperatures will damage your **EXTREME RAGE X-RAY® PROTECTOR** Goggles and Lenses.

E) Always inspect your **EXTREME RAGE X-RAY® PROTECTOR** Goggles and Lenses for damage prior to and after each game you play and replace as required. Never play with a lens that shows any signs of damage including but not limited to cracking, pitting or deep scratches.

F) Always immediately replace any **EXTREME RAGE X-RAY® PROTECTOR** Lens that has been shot by a marker at a range of 10 feet or less. (Even if you cannot see any sign of damage)

G) Always replace each **EXTREME RAGE X-RAY® PROTECTOR** Lens at least once a year even if you have not used them.

WARNING! The **EXTREME RAGE X-RAY® PROTECTOR** Mask, frame, lens, head armor, strap, lens retaining pin, chin strap and visor are specifically designed for use with the **EXTREME RAGE X-RAY® PROTECTOR** Goggle System only. Never use the **EXTREME RAGE X-RAY® PROTECTOR** Goggle System without all components installed. Non-use or removal of chin strap increases your risk of injury.



ALWAYS PLAY SAFE! OBSERVE RULES OF SAFE PLAY AND RULES OF PAINTBALL MARKER HANDLING. PAINTBALL IS AN EXTREME ACTION SPORT. BE ADVISED EXTREME RAGE PROTECTIVE EQUIPMENT CANNOT PREVENT SERIOUS INJURIES UNDER ALL CONDITIONS.

- 1) NEVER remove, lift or take off your **EXTREME RAGE X-RAY® PROTECTOR** Goggle System from your face for any reason while you are in an active paintball area. EVEN WHEN YOU ARE NOT PLAYING! If you remove your **EXTREME RAGE X-RAY® PROTECTOR** Goggle System off your face, it cannot protect you!
- 2) Always use an approved barrel-blocking device on your marker when not in use.
- 3) Do not play or use **EXTREME RAGE X-RAY® PROTECTOR** Goggle Systems if paintball velocities exceed 300 feet per second. All paintball markers must be chronographed prior to use.
- 4) Always check that your lens is properly installed prior to using your goggle system.
- 5) Always inspect your lens for damage and replace as required, prior to and after each game you play. Never play with a lens that shows any signs of damage including but not limited to cracking, pitting or deep scratches.
- 6) Always immediately replace any lens that has been shot by a marker at a range of 10 feet or less.
- 7) Always replace each lens at least once a year.
- 8) Always follow all cleaning and user instructions exactly. Improper use or maintenance of your **EXTREME RAGE X-RAY® PROTECTOR** Goggle System may result in serious eye injury, blindness or death.
- 9) Always wear your **EXTREME RAGE X-RAY® PROTECTOR** Goggle System whenever shooting a paintball marker and whenever in or near an area where paintball markers are being shot.
- 10) No goggle can prevent fogging under all conditions. If your goggle does fog, **do not remove it while on the field.**
- 11) Always store your **EXTREME RAGE X-RAY® PROTECTOR** Goggle System in a cool dry place. Never store your goggle system near chemicals or fumes. Gasoline fumes and common cleaning solutions will damage your **EXTREME RAGE X-RAY® PROTECTOR** Goggle System and lens. Replace any lens that has been exposed to these conditions.

NEVER REMOVE YOUR GOGGLES WHILE ON OR NEAR A PAINTBALL FIELD OR TARGET RANGE

EXTREME RAGE X-RAY® PROTECTOR APPLICATION

Figures A-D

- 1) Rotate the rear armor plate up to create enough room for your head. Figure A. Place your head inside the goggle and tighten both the goggle strap (See Figures E-F) and chin strap (See Figures 7-9).
- 2) Rotate the rear armor plate back down so it encloses your entire head and the velcro locks it in place. Figure B.
- 3) To remove the armor plates, begin by unsnapping the forwardmost snap on each side near the lens to remove the rear plate. Figure C. Then unsnap the remaining two snaps on each side of the goggle to remove the top armor plate. Figure D.



Fig. A



Fig. B



Fig. C



Fig. D

EXTREME RAGE X-RAY® PROTECTOR GOGGLE FIT

Goggles must fit properly to provide best protection. Proper fit requires

- A) Tightening strap to hold goggle system firmly in place on head.
- B) Making certain the goggle seals all around the face.

IMPORTANT! The **EXTREME RAGE X-RAY® PROTECTOR** goggle system has a strap, which allows variations in head size and fit. The plastic strap adjusting slides can be positioned outside or inside the mask assembly for proper fit.

To move the two strap adjusting slides inside the mask assembly, simply turn and slide the straps **out** of the mask strap channels. (Fig. A) This is recommended for users under the age of 18.

To move the two strap adjusting slides outside the mask assembly, turn and slide the straps **into** the mask strap channels. (Fig. B) Adjust the slides as required.



Fig. E
Straps Outside Channel



Fig. F
Straps Inside Channel

VISOR ATTACHMENT

Figure 1–2

- A) Wet ends of visor posts.
- B) Push right hand post through mounting hole in mask.
- C) Push left hand post through mounting hole in mask.
- D) Rotate visor and push center post through mounting hole in front of mask

WARNING! Once installed, do not attempt to remove visor. Damage may occur. Never use the **EXTREME RAGE X-RAY® PROTECTOR** Goggle System without all components installed.



Fig. 1



Fig. 2

FACE MASK ATTACHMENT

Figure 3-4

- A) Insert frame into facemask from front.
- B) Align two lower inner nose mask posts with two inner mounting holes on bottom of frame. Push frame and mask together until posts are completely in frame.
- C) Align two lower outer nose mask posts with two outer mounting holes on bottom of frame. Push frame and mask together until posts are completely in frame.
- D) Align three upper mask posts with three inner mounting holes on top of frame. Push frame and mask together until posts are completely in frame.
- E) Reverse process to remove frame from mask.



Fig. 3



Fig. 4

STRAP ATTACHMENT

Figure 5–6

- A) Slide end of strap through frame strap slot on right hand side of frame. Make sure printed side of strap is to outside of goggle.
- B) Slide strap-retaining pin through goggle strap channel until it is completely through strap.
- C) Make certain goggle strap-retaining pin is exposed and even amount on each side of the strap prior to use.
- D) Repeat process for left hand side of goggle with other end of strap.



Fig. 5



Fig. 6



Fig. 7



Fig. 8



Fig. 9

CHIN STRAP ATTACHMENT

Figure 7–9

- A) Fasten strap to goggle frame using snaps located inside goggle frame.
- B) Fasten buckle, inserting male prongs in to the female portion until you hear a click.
- C) Adjust chin strap snugly under your chin. To unfasten buckle squeeze male prongs to eject from female portion.

LENS REPLACEMENT



Fig. 10



Fig. 11



Fig. 12

LENS REMOVAL (All Types)

Figures 10–13

- 1) Separate goggle frame from mask. See instructions under attaching facemask for further details. (Fig. 3-4)
- 2) Peel away frame from lens starting from top left hand side of frame. Do not use any tools to remove lens.
- 3) Work your way around to the bottom of the frame and remove lens completely from the frame.



Fig. 13

LENS INSTALLATION (All Types)

Figures 12–13

- 1) Do not put a lens in a dirty frame. Clean frame completely prior to installing any lens.
- 2) Insert lens into bottom groove of frame.
- 3) Work lens into frame groove around bottom first and continue until lens is installed in frame.
- 4) Push all lens retention tabs completely through frame until lens is secured.
- 5) Make certain the nose, lower frame and top frame lens tabs are securely locked into the goggle frame.
- 6) Reinstall the goggle frame into the facemask. See instructions under attaching facemask for further details.

CAUTION

Improper installation of facemasks, lens, head armor or straps can cause an eye injury. Follow all installation instructions closely. Use only **EXTREME RAGE X-RAY® PROTECTOR** Goggles with **EXTREME RAGE** Facemasks, lens and straps. Never use the **EXTREME RAGE X-RAY® PROTECTOR** Goggle without the facemask. Make certain the facemask is properly installed and securely attached to the goggle. Always wear ear protection when playing paintball. Goggle straps are not ear protectors. The **EXTREME RAGE X-RAY® PROTECTOR** Goggle System has been specifically designed to be used in the sport of paintball. Paintball is a sport that, like all sports, has intrinsic hazards. These hazards include being hit by paintballs. Protective equipment cannot eliminate all injuries but will substantially reduce their severity and frequency. Participation in the sport of paintball by a player implies acceptance of the risk of injury. The goal of protective equipment is to minimize the risk of injury.