



WARNING

DO NOT USE UNTIL ALL INSTRUCTIONS
REGARDING SAFETY HAVE BEEN READ.

SENTRY[®]
VISION SYSTEM

**Use and Care Instructions
for Vision System with
Extended coverage**

One size fits all - Fits adult size: S / M / L



This product meets ASTM standards F 1776

CONGRATULATIONS !

Your new SENTRY® by VFORCE™ combines solid durability protection and comfort in a unibody constructed mask with the thickest shell in it's class. This mask protects from both 50cal and 68cal paintballs.

The renowned and reliable ARMOR™ lens design ensures distortion-free vision, enhancing your rapid target-acquisition efficiency and overall safety.

The unique Quick-Change™ system allows you to remove the lens, eye foam, and strap in seconds for cleaning or interchanging so you are quickly back in the game.

An integrated visor protects from sunny conditions and doubles as a protective lens guard should your mask be off and accidently thrown about.

Includes a built-in chin strap that keeps your mask super secure throughout play.

A Free-Flow ventilated design ensures maximum breathability in every playing condition.

Have fun, look great and always Play Safe!

WARNING

Read and follow carefully all instructions and warnings contained in this manual. Failure to observe all instructions and warnings could lead to severe or permanent injuries.

Remember that your mask cannot offer protection in all situations

- Always wear your mask with visor and chin strap securely attached as per instructions.
- NEVER remove your mask in the playing area, even if the lens fogs or gets dirty. If your mask accidentally comes off, throw yourself on the ground and protect your eyes. Tell the players to stop shooting and ask the referees or one of the other players to help you leave the area with your eyes covered.
- Before the beginning of the game, all paintball markers must be chronographed to ensure that the speed of the paintballs does not exceed 300 f.p.s. (91 m/s). Higher speeds could exceed the resistance limits of your mask and lead to serious or permanent injury. Do not play if the speed of the paintballs exceeds 300 f.p.s., or if speed is not verified.
- Always follow all safety rules regarding the game and the handling of paintball markers.
- In rare cases, any mask may cause irritation and should not be worn by persons who are subject to dermatitis.

Discontinue the use of the mask immediately in case of irritation and consult your physician.

WARNING

This Vision System provides Extended Coverage as defined in ASTM standard F1979. This Vision System is designed to fit users of Adult Sizes Small, Medium and Large

TABLE OF CONTENTS

Fitting	4
Mask and Lens Care	5
Lens Removal	6
Lens & Eye Foam Removal	7
Eye Foam Installation	8
Lens Installation	9
Chip Strap Installation	10

FITTING

Check that the strap is inserted properly in the slots provided in the mask, and that it fits snugly around your head. Ensure that the foam around the lenses sits properly around your eyes. Ensure that the visor is also properly installed to the frame as per the instructions.

WARNING

Wear your paintball protective Vision System at all times when playing, practicing or target shooting.

WARNING

Before each game, breathe on the inside surface of the lens.
If it fogs up: before using your mask - replace the lens or treat it with VForce Anti-Fog Solution.

MASK AND LENS CARE

Your Sentry mask has a single pane polycarbonate lens that has been treated with a Thermo-Cured Anti-Fog coating. Further information on the lenses is provided in the last section of this manual.

CLEANING

- Clean your lens within two hours of any contact with paintball residues. Remove the lens to ensure that all lens and mask surfaces are thoroughly cleaned.
- Use only warm water or VForce anti-fog solution to clean the lens. Do not use any other products, as they may contain substances that may weaken the lens. Change the lens if it has come in contact with any chemical products or fumes.
- Use only a clean soft cloth to clean the lens. Avoid the use of substances that could scratch or dull the lens, such as newspaper, paper towels, dish towels or clothing. It is normal for the anti-fog coating on the inside surface to go through a tacky phase while drying. To clean this surface, pat it with a moist cloth and let it dry. Do not wipe the inside surface - it will streak and you will have to clean the lens again.

ANTI-FOG TREATMENT

- Despite the extra-long life span of the VForce Anti-Fog, with time, all anti-fog treatments eventually lose effectiveness. If this happens, USE ONLY VForce Anti-Fog solution to reactivate. Do not use any other products, since their chemicals may weaken the lens.

STORAGE

- Ensure that your Sentry mask by VForce is clean, before storing it. Protect the lens against impacts and scratches. Store your mask in a cool, clean and dry place, far from chemical products or fumes and protected from high temperatures.


LENS REMOVAL

SENTRY



- 1 Push inner temple clip firmly upwards with your thumb while holding top of mask securely with both hands.

- 2 Once clip slides off repeat step on other side of mask.




- 3 Remove fastening clips from both sides of lens by pushing each clip from the inside of mask with your fingers releasing and sliding the clip from under the lens with your free hand.

WARNING

Check lens before each and every use. Replace the lens after one year of use even if it seems to be perfect. Replace lens immediately if it shows cracks or if it has received a direct impact from a ball shot a distance of less than 10 feet (3m)


LENS REMOVAL

SENTRY




- 4 Press on the fastening tab (edge of lens temple area) to dislodge the lens from mask.

- 5 Repeat step on opposite side and remove lens from mask.



EYE FOAM REMOVAL




- 1 Once all clips, fasteners and lens are removed the Eye Foam can simply be popped out by pulling it from its support slots.

WARNING

Use only lenses specifically designed for this vision system model.


EYE FOAM INSTALLATION

SENTRY



- 1 Insert EyeFoam by resting one side first on support slot.



- 2 Angle EyeFoam from support slot on one side then snap into opposite support slot. When secured you will hear audible "click" sound.



LENS INSTALLATION

SENTRY

- 1 Insert new lens making sure that both fastening tabs are fully inserted and securely in place. Ensure that both upper positioning tabs are inserted in their respective slots.




- 2 Reinsert fastening clips by sliding and snapping them under the lens temple tabs.

WARNING

Ensure that the lens is firmly in place before wearing the mask.
Do not make and modifications to your mask.
Use only accessories that have been approved for your Sentry mask
by VForce. (The retention strap is not an ear protector.)


CHIN STRAP INSTALLATION

SENTRY



- 1 To properly fasten the buckle insert the "male" prongs into the "female" portion until you hear an audible "click". Adjust strap to fit snugly under your chin.

- 2 Unfastening the buckle is accomplished by squeezing the right and left edges of the "male" prongs until they are automatically ejected from the "female" portion.



WARNING

NEVER play a game of paintball
without the chin strap securely attached to the mask.

SENTRY®

VISION SYSTEM

Meets or exceeds
International Standards for:



This model is certified by: SAI Global Assurance Services Ltd.
Partis House, Ground Floor, Davy Avenue, Knowlhill, Milton Keynes
MK5 8HJ, United Kingdom - Notified Body Number: 2056



VFORCE VISION SYSTEMS
6000 Kieran, St-Laurent, Quebec, Canada
www.vforce.com

MADE IN CHINA
VFORCE™ and SENTRY® are Registered Trademarks